OUT51779

Declassification Review by

NGA/DoD

D1 **1949**Z

FM CIA VASNDC

TO RUCSBR/SAC OFFUTT AFB. ONAHA, NEB RUCVAB/4868 STRAT WG, OL 19, BARKSDALE AFB, LA RMEANQ/DIAXX

RECYS/HAVY PIC

RUUBKS/15TH AF, MARCH AFB, RIVERSIDE, CALIF RUNGAA/2D RTS, BARKSDALE AFB, LA RUWGAA/2AF, BARKSDALE AFB, LA

DA SENC

BT

SECRET

CITE CIA-Z-855

15TH AF (FOR DI); SAC (FOR DIN, BRASS KNOB, DOCR, DM 4), 2D AF (FOR DI). FROM NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER.

1. CAMERA B-15 WAS USED IN MISSION 3784 FLOWN ON 28 AUGUST 1963; PROCESSING WAS ACCOMPLISHED BY HAVY PIC.

## 2. ORIGINAL MEGATIVE:

- THE RESOLUTION IS GOOD AND THE EXPOSURE IS ADEQUATE.
- OR SIDE: A FINE PLUS DENSITY STREAK APPEARS INTER-HITTENTLY 3.3" FROM AND PARALLEL TO THE OUTBOARD EDGE THROUGHOUT THE MISSION. A MINUS DENSITY STREAK IS NOTED APPROXIMATELY 1" FROM AND PARALLEL TO THE INBOARD EDGE ON FRAMES 1487, 1489, 1778, 1779 AND 1786. A MEAT SPLICE IS PRESENT THROUGH FRAME 611. TRANSVERSE BANDING TYPE STATIC AND ASSOCIATED DENDRITIC TRACES

GROUP 1 Excluded from automatic dewngrading and declassification

Approved For Release 2008/03/07 -RDP78B04558A000700110050-8 APART AND EXTENDS 1" TO 6" INTO THE FORNAT AREA FROM THE INBOARD EDGE. A MANUFACTUER'S SPLICE IS PRESENT THROUGH FRAME 991 AND SLIGHT FORGING OCCURS ADJACENT TO THIS SPLICE. TWO FORGED PATCHES ARE NOTED ALONG THE OUTBOARD EDGE THROUGHOUT THIS HISSION. THE FIRST FORGED PATCH IS NOTED ON FRAME 743 AND IS APPROXIMATELY 1 SQUARE INCH; THE OTHER PATCH IS NOTED ON FRAME 1140 AND IS APPROXIMATELY 5 SQUARE INCH; THE SCRATCH IS PRESENT 2.7" FROM AND PARALLEL TO THE INBOARD EDGE ON FRAMES 2352 THROUGH 2369 (END OF THE MISSION).

- C. 9L SIDE: THREE ROWS OF MINUS DENSITY BOTS SPACED 1.55"

  APART ARE PRESENT 0.28", 0.2" AND 0.32" RESPECTIVELY FROM AND PARALLEL

  TO THE IMBOARD EDGE THROUGHOUT THIS SIDE. INBOARD ROLLER CHATTER

  AND IMBOARD EDGE STATIC OCCUR THROUGHOUT THIS MISSION. A PLUS

  DENSITY STREAK IS PRESENT 3.15" FROM AND PARALLEL TO THE OUTBOARD

  EDGE ON FRAMES 1155 THROUGH 2369 (END OF THE MISSION). THIS STREAK

  SPLITS AT APPROXIMATELY FRAME 1400 AND BECOMES 2 PARALLEL PLUS DENSITY

  STREAKS 0.15" APART AND GRADUALLY FORMS A STREAK AGAIN.
- D. THERE WERE NO HAJOR CAMERA HALFUNCTIONS OR PROCESSING PROBLEMS ENCOUNTERED DURING THIS HISSION.
  - 3. POSITIVE:
- A. PI SWITABILITY IS GOOD. VATER SPOTS ALONG THE INBOARD EDGE ARE NOTED ON APPROXIMATELY THE FIRST 188 FRANES OF THE 9L SIDE. NO PRINTING OR PROCESSING PROBLEMS OTHER THAN THE ABOVE

MENTIONED WATER SPOTS WERE ENCOUNTERED DURING THIS HISSION.

B. CLOUDS OBSCURED APPROXIMATELY 38 PER CENT OF THIS HISSION.
SECRET

END OF MESSAGE

(ABOVE HESSAGE ALSO PASSED TO CLA VATCH (ASP/RR))